

# intel® Technical Advisory

TA-704-1

5200 NE Elam Young Parkway  
Hillsboro, OR 97124

July 28, 2004

## Intel® E7520 MCH Transposed Interrupt Messages across Hub Interface Erratum: Impact to Intel® Server Board SE7520BD2

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice. The **Intel Server Board SE7520BD2** may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

### Products Affected

| Product Code  | MM #   |
|---------------|--------|
| SE7520BD2SCSI | 858594 |
| SE7520BD2V    | 863222 |
| SE7520BD2     | 858586 |
| BBDBBSCSI     | 861103 |
| BBDVBB        | 858578 |
| BBDBBSATA     | 863169 |

### Description

An erratum affecting PCI Express\* slot capabilities has been found in the Intel® E7520 server chipset during testing and is root caused. Please reference *Intel® E7520 MCH Specification Update Erratum #23: "Transposed Interrupt Messages across Hub Interface Erratum"* for a complete description of the MCH errata. The Intel® Server Board SE7520BD2 is affected by this erratum.

Intel Server Board SE7520BD2 based systems running with a single processor thread and operating in legacy PIC mode or virtual wire Mode A may hang under high I/O-driver interrupt stress. For systems operating in full APIC mode where the number of virtual interrupt line (intA, intB, etc.) used by all PCI-Express\* adapters in a system exceeds the number of logical processors (threads), the system may hang.

### Root Cause

Please reference *Intel® E7520 MCH Specification Update Erratum #23: "Transposed interrupt messages across Hub Interface Erratum"* for a complete description of the MCH errata.

### Corrective Action / Resolution

PCI Express adapter add-in cards are not recommended for use with Intel Server Board SE7520BD2. All PCI Express devices down on the server board are supported. A BIOS workaround is required for PIC mode operation. The BIOS workaround will be incorporated into Intel Server Board SE7520BD2 BIOS Production Release Version P03.10. Intel recommends that customers update all Intel® Server Board SE7520BD2 to this BIOS version. BIOS Version P03.10 will be available from iBL and <http://support.intel.com> on or before September 24, 2004.

Customers may choose to ship Intel Server Board SE7520BD2 product with BIOS Production Release Version P02, which does not include the PIC mode BIOS workaround, if the system configuration adheres to the following limitations: 1) Uni-processor systems must have processor hyperthreading Enabled in BIOS Setup, 2) The operating system must be

# intel<sup>®</sup> Technical Advisory

TA-704-1

5200 NE Elam Young Parkway  
Hillsboro, OR 97124

July 28, 2004

configured to operate in symmetric mode rather than PIC mode, and 3) No PCI Express adapter add-in cards are installed. This restricted configuration will limit any possible exposure to this issue to pre operating system boot.

An MCH component stepping change will be implemented on the Intel Server Board SE7520BD2 in early Q4 2004 to add support for broad PCI Express\* adapter add-in cards.

Please contact your Intel Sales Representative if you require more specific information about this issue.

Enterprise Platforms & Services Division  
Intel Corporation