











```
Ld    !r2,*.HIBYTE. RdBik_Vector
Ld    !r3,*.LOWBYTE. RdBik_Vector
Call  Bank_Call
Pop   !r5
Jr    Nz,RwTest_End

Tm    !r0,#RdNoHdrFnd
Jr    Nz,Rw_Next
Ld    !r0,RdErrCnt
And   !r0,#$0F ;mask off unwanted status
Cp    !r0,#10
Jr    Nz,RwTest_End
```

```
Rw_Next:  Inc    Sector
          Djnz  !r5,RwTest_Lp
```

```
RwTest_End:  Ld    !r2,*.HIBYTE. Park_Heads
             Ld    !r3,*.LOWBYTE. Park_Heads
             Call  Bank_Call

             Pop   Excpt_Stat ;recover original exception state
             Or    !r5,!r5 ;set zero flag
             Ret
```

```
.LSTOFF
```