

# Matrox® **Display Driver Release Notes**

For display driver version 4.05.00 (WDDM Beta for Windows® 10)

20116-401-0114  
2015.12.10

[www.matrox.com/graphics](http://www.matrox.com/graphics)

**matrox**®  
Graphics for Professionals

---

# Contents

<b>1</b>	<b>Overview .....</b>	<b>3</b>
<b>2</b>	<b>Driver Changes in Version 4.05.00 .....</b>	<b>4</b>
	Notes and limitations.....	4
<b>3</b>	<b>Display Driver Information.....</b>	<b>5</b>
	Display driver .....	5
	Supported languages.....	5
	Downloading the display driver .....	5
	Installing the display driver .....	5
<b>4</b>	<b>Contact Us .....</b>	<b>6</b>
<b>5</b>	<b>Disclaimer .....</b>	<b>7</b>

---

# 1 Overview

This document describes the current release of the Matrox display driver (v. 4.05.00) for Microsoft® Windows® operating systems. Matrox provides these notes to describe bug fixes and improvements to PowerDesk software and to the display driver.

---

# 2 Driver Changes in Version 4.05.00

---

## Notes and limitations



**Note:** Matrox Extio F2208, F2408, and F2408 Expander don't support UEFI Boot Mode. Enabling UEFI Boot Mode will cause your system to behave erratically. To avoid possible issues, make sure you enable Legacy BIOS Boot Mode.

- Corruption occurs when running Google Earth 6.22 or later. For a possible workaround, contact Matrox Technical Support.
- While using multiple input sources on your DisplayPort™ monitor (for example, connecting to the DisplayPort connector *and* a DVI, HD-15, or other connector on your monitor), certain models of DisplayPort monitors (such as Lenovo®) may not be properly detected. To fix this, we recommend disconnecting the non-DisplayPort connections from your DisplayPort monitor.
- While using two graphics cards in joined mode, edge overlap isn't supported.
- While using two Matrox M9188 graphics cards in joined mode with certain HP® systems (xw6400, xw6600, xw8400, and xw8600), not all 16 outputs may be available. To fix this, we recommend changing the configuration of your computer BIOS so that the slot type of your secondary Matrox M9188 graphics card has priority for becoming the primary display. For information on how to change your computer BIOS settings, see your system manual.
- After changing modes, Windows Media Player may occasionally be unable to play content. You can work around this by restarting your system.
- While using Microsoft® Office 2016 (or other programs), certain **Desktop Management** features may not work.
- Each layout in your multi-display setup supports a maximum resolution of 4Kx4K.
- The **Split display** shortcut may not work in joined mode.
- While using the Japanese version of Windows 10, PowerDesk may unexpectedly stop working after multi-display settings are applied.

---

# 3 Display Driver Information

---

## Display driver

This package contains drivers for the following products.

Supported hardware	Supported operating systems (4.05.00 Beta, no WHQL)
M-Series™	Windows® 10 (32-bit, 64-bit)
Extio™ Series (F2208, F2408, and F2408 Expander only)	

---

## Supported languages

This driver package supports the following languages:

- English, French, German, Italian, Spanish

---

## Downloading the display driver

Matrox makes the latest display drivers available on the Matrox Web site ([www.matrox.com/graphics/support/drivers](http://www.matrox.com/graphics/support/drivers)).

---

## Installing the display driver

If a CD was provided with your Matrox product, insert the Matrox installation CD-ROM in your CD-ROM drive, and follow the on-screen instructions.

If a CD wasn't provided with your Matrox product, download the latest display driver from the Matrox Web site, and follow the on-screen instructions to install your display driver.

---

## 4 Contact Us

The Matrox Web site has product literature, press releases, technical material, a sales office list, trade show information, and other relevant material. Visit us at [www.matrox.com/graphics](http://www.matrox.com/graphics).

If you have any questions or comments about our products or solutions, contact us at [www.matrox.com/graphics/contact](http://www.matrox.com/graphics/contact).

---

## 5 Disclaimer

Information in this document may contain technical inaccuracies or typographical errors. Information may be changed or updated without notice. Matrox reserves the right to make improvements and/or changes in the products, programs and/or specifications described in this information at any time without notice. All trademarks and trade names, service marks and logos referenced herein belong to their respective owners.

DisplayPort is a trademark of VESA.

HP is a registered trademark of Hewlett-Packard Company.

Lenovo is a registered trademarks of Lenovo in the United States, in other countries, or both.

Microsoft and Windows are either registered trademarks or trademarks of Microsoft Corporation in the United States and/or other countries.

Copyright © 2015 Matrox is a registered trademark of Matrox Electronic Systems Ltd. All rights reserved.

**Matrox Graphics Inc.**

1055 Saint Regis Boulevard  
Dorval, Quebec, Canada H9P 2T4

North America: 1-800-361-1408

International: (514) 822-6000

Email: [graphics@matrox.com](mailto:graphics@matrox.com)

Web site: [www.matrox.com/graphics](http://www.matrox.com/graphics)

Technical support:

[www.matrox.com/graphics/support](http://www.matrox.com/graphics/support)

To locate the sales office nearest you, visit

[www.matrox.com/graphics/contact](http://www.matrox.com/graphics/contact)

**matrox**<sup>®</sup>  
Graphics for Professionals