## **Erratum**

In "System Development and Technology Aspects of the IBM 3081 Processor Complex" (M. S. Pittler, D. M. Powers, and D. L. Schnabel, *IBM Journal of Research and Development* 26, No. 1, January 1982, pp. 2–11), the following change should be noted:

p. 3 The unit of power in the last column in Table 1 should be kilovoltamperes (kVA) instead of kilowatts.